






序号	报告编号	发布日期	结论	影像资料	
407	GX-B1361/22-A-23977	2023/9/27	所检项目合格		
408	GX-B1361/22-A-23978	2023/9/27	所检项目合格		



序号	报告编号	发布日期	结论	影像资料
409	GX-B1361/22-A-23979	2023/9/27	所检项目合格	
410	GX-B1361/22-A-23980	2023/9/27	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
411	GX-B1361/22-A-23981	2023/9/27	所检项目合格	
412	GX-B1361/22-A-23982	2023/9/27	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
413	GX-B1361/22-A-23983	2023/9/27	所检项目合格	
414	GX-B1361/22-A-231009	2023/9/27	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
415	GX-B1361/22-A-231010	2023/9/27	所检项目合格	 A photograph showing a worker in a light-colored uniform operating a lathe machine in a workshop. The worker is leaning over the machine, which is mounted on a wooden stand. In the background, another worker is visible near a window with yellow curtains. A yellow timestamp '2023/9/26' is located in the bottom right corner of the image.
416	GX-B1361/22-A-231011	2023/9/27	所检项目合格	 A photograph showing a worker in a light-colored uniform inspecting a part on a workbench. The worker is wearing white gloves and holding a green flashlight. In the background, another worker is visible near a window with yellow curtains. A yellow timestamp '2023/9/26' is located in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
417	GX-B1361/22-A-23893	2023/9/28	不合格	
418	GX-B1362/20-A-23365	2023/9/28	合格	

序号	报告编号	发布日期	结论	影像资料
419	GX-B1362/20-A-23366	2023/9/28	合格	
420	GX-B1362/20-A-23367	2023/9/28	不合格	

序号	报告编号	发布日期	结论	影像资料
421	GX-B1362/20-A-23368	2023/9/28	不合格	
422	GX-B1362/20-A-23369	2023/9/28	合格	



序号	报告编号	发布日期	结论	影像资料
423	GX-B1362/20-A-23370	2023/9/28	合格	
424	GX-B1361/22-A-23932	2023/9/28	不合格	

序号	报告编号	发布日期	结论	影像资料
425	GX-B1361/22-A-23933	2023/9/28	不合格	