

序号	报告编号	发布日期	结论	影像资料
20	GX-B1600/21-F-23025	2023. 11. 30	可不注水煤层	
21	GX-B1600/21-F-23026	2023. 11. 30	可不注水煤层	
22	GX-B1600/21-F-23023	2023. 11. 30	可注水煤层	
23	GX-B1600/21-F-23024	2023. 11. 30	可注水煤层	
24	GX-B1377/22-F-23296	2023. 11. 24	所检项目合格	 A photograph showing two individuals, likely laboratory staff, standing in a laboratory or office environment. They are wearing grey lab coats and face masks. They are positioned next to a desk with various pieces of equipment, including a computer monitor, a printer, and other electronic devices. The date '2023/11/23' is visible in the bottom right corner of the image.

25	GX-B1377/22-F-23297	2023. 11. 24	所检项目合格	 A photograph showing two female technicians in grey lab coats and face masks working in a laboratory. They are positioned around a piece of scientific equipment with a large, open lid. The technician on the right is looking into the equipment, while the one on the left is looking towards the camera. The background features a window with yellow curtains. A small timestamp '2023/11/23' is visible in the bottom right corner of the image.
26	GX-B1377/22-F-23295	2023. 11. 24	所检项目合格	 A photograph showing two female technicians in grey lab coats and face masks standing in a laboratory. They are positioned next to a long table covered with a green cloth, which holds several pieces of scientific equipment, including a large white instrument and a computer monitor. The technician on the left is looking towards the equipment, while the one on the right is looking towards the camera. The background is a plain white wall. A small timestamp '2023/11/23' is visible in the bottom right corner of the image.

27	GX-B1378/22-F-23248	2023. 11. 24	所检项目合格	
----	---------------------	--------------	--------	---