

序号	报告编号	发布日期	结论	影像资料
12	GX-B1521/20-Y-23627	2023年12月5日	所检项目合格。	 A photograph showing a worker wearing a red hard hat and a safety vest, looking at a document or equipment. The background is a complex structure of pipes and metal. A yellow timestamp '2023/11/28' is visible in the bottom right corner of the image.
13	GX-B1521/20-Y-23628	2023年12月5日	所检项目合格。	 A photograph showing a worker in a red hard hat and safety vest operating a piece of machinery, possibly a forklift or a similar vehicle. The worker is seated and looking down at the controls. A yellow timestamp '2023/11/28' is visible in the bottom right corner of the image.

14	GX-B1539/20-Y-23273	2023年12月5日	所检项目合格。	 A yellow wheel loader with the number '04' on its side. Two workers in safety gear are standing in front of the machine. A yellow timestamp '2023/11/28' is visible in the bottom right corner of the photo.
15	GX-B1539/20-Y-23274	2023年12月5日	所检项目合格。	 A yellow wheel loader with the number '05' on its side. Two workers in safety gear are standing in front of the machine. A yellow timestamp '2023/11/28' is visible in the bottom right corner of the photo.

16	GX-B1522/20-Y-23146	2023年12月4日	所检项目合格。	
17	GX-B1563/21-Y-23045	2023年12月5日	所检项目合格。	

18	GX-B1423/20-Y-236286	2023年12月4日	综合判定：合格	 <p>A yellow MT858 dump truck is shown from a front-three-quarter view. Two workers in work clothes and hard hats stand in front of the truck. The truck has 'MT858' and '09' visible on its side. A yellow timestamp '2023/11/28' is in the bottom right corner.</p>
19	GX-B1423/20-Y-236287	2023年12月4日	综合判定：合格	 <p>A yellow MT858 dump truck is shown with its bed raised. Two workers in work clothes and hard hats stand in front of the truck. The truck has 'MT858' and '09' visible on its side. A yellow timestamp '2023/11/28' is in the bottom right corner.</p>

20	GX-B1423/20-Y-236288	2023年12月4日	综合判定：合格	 A yellow dump truck is parked on a paved surface. Two workers in work clothes and hard hats are standing in front of the truck. The truck has a red number '10' on its side. A yellow timestamp '2023/11/28' is visible in the bottom right corner of the photo.
21	GX-B1423/20-Y-236289	2023年12月4日	综合判定：合格	 A yellow dump truck is parked on a paved surface. Two workers in work clothes and hard hats are standing in front of the truck. The truck has a red number '11' on its side. A yellow timestamp '2023/11/28' is visible in the bottom right corner of the photo.

22	GX-B1306/23-Y-23147	2023年12月4日	综合判定：合格	
23	GX-B1306/23-Y-23148	2023年12月4日	综合判定：合格	

24	GX-B1306/23-Y-23149	2023年12月4日	综合判定：合格	
25	GX-B1306/23-Y-23150	2023年12月4日	综合判定：合格	

26	GX-B1306/23-Y-23151	2023年12月4日	综合判定：合格	 A photograph showing a worker in a dark uniform and a red hard hat inspecting a large, grey electrical cabinet. The worker is holding a microphone. The cabinet has a red label on top that reads '10kV 开关柜' (10kV Switchgear). A yellow timestamp '2023/11/27' is visible in the bottom right corner of the photo.
27	GX-B1306/23-Y-23152	2023年12月4日	综合判定：合格	 A photograph showing a worker in a dark uniform and a red hard hat inspecting a large, grey electrical cabinet. The worker is holding a microphone. The cabinet has a red label on top that reads '10kV 开关柜' (10kV Switchgear). A yellow timestamp '2023/11/27' is visible in the bottom right corner of the photo.

28	GX-B1416/22-Y-23090	2023年12月5日	综合判定：合格	
29	GX-B1416/22-Y-23091	2023年12月5日	综合判定：合格	
30	GX-B1308/23-Y-23113	2023年12月1日	综合判定：合格	

31	GX-B1559/22-Y-23020	2023年12月5日	所检项目合格。	
----	---------------------	------------	---------	---