

序号	报告编号	发布日期	结论	影像资料
20	GX-B1361/22-A-231162	2023/12/5	所检项目合格	
21	GX-B1361/22-A-231184	2023/12/5	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
22	GX-B1361/22-A-231185	2023/12/5	所检项目合格	
23	GX-B1361/22-A-231186	2023/12/5	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
24	GX-B1361/22-A-231187	2023/12/5	所检项目合格	
25	GX-B1361/22-A-231261	2023/12/1	合格	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1361/22-A-231190	2023/12/6	合格	
27	GX-B1361/22-A-231191	2023/12/6	合格	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1361/22-A-231188	2023/12/6	所检项目合格	
29	GX-B1361/22-A-231189	2023/12/6	不合格	

序号	报告编号	发布日期	结论	影像资料
30	GX-B1361/22-A-231192	2023/12/6	所检项目合格	
31	GX-B1361/22-A-231193	2023/12/7	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1361/22-A-231194	2023/12/6	合格	
33	GX-B1361/22-A-231195	2023/12/6	合格	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1361/22-A-231196	2023/12/6	合格	 A photograph showing two men in light-colored work jackets operating a large industrial machine in a workshop. The man on the left is wearing gloves and appears to be adjusting or working on a component of the machine. The man on the right is looking down at the machine. The machine is a large, light-colored metal structure with various components and a control panel. In the background, there is a wooden chair and some equipment on a table. A yellow timestamp "2023/11/14" is visible in the bottom right corner of the image.