


序号	报告编号	发布日期	结论	影像资料
77	GX-B1428/21-P-23040	2023. 12. 18	无缺陷痕迹显示。	
78	GX-B1428/21-P-23041	2023. 12. 18	无缺陷痕迹显示。	

79	GX-B1310/21-P-23163	2023. 12. 18	符合标准要求。	
80	GX-B1310/21-P-23164	2023. 12. 18	符合标准要求。	
81	GX-B1416/22-P-23123	2023. 12. 19	综合判定：合格。	

82	GX-B1495/20-P-231171~231173	2023年12月19日	本次共检高压开关柜3台，3台高压开关柜所检项目合格。	
83	GX-B1495/20-P-231174~231177	2023年12月19日	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	
84	GX-B1328/20-P-23079~23080	2023年12月20日	本次共检绝缘手套32只，绝缘鞋32只，所检项目合格。	

85	GX-B1495/20-P-231174~231177	2023年12月19日	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	
86	GX-B1310/21-P-23160	2023. 12. 20	符合标准要求。	 A photograph showing a worker in a blue protective suit and red helmet working on a high-voltage switchgear cabinet. The worker is positioned on a metal structure, and the background shows industrial equipment. A timestamp '2023.11.26' is visible in the bottom right corner of the image.
87	GX-B1310/21-P-23161	2023. 12. 20	符合标准要求。	 A photograph showing a worker in a blue protective suit and white helmet working on a high-voltage switchgear cabinet. The worker is positioned on a metal structure, and the background shows industrial equipment. A timestamp '2023.11.26' is visible in the bottom right corner of the image.

88	GX-B1310/21-P-23162	2023. 12. 20	符合标准要求。	
89	GX-B1310/21-P-23165	2023. 12. 20	符合标准要求。	
90	GX-B1310/21-P-23166	2023. 12. 20	符合标准要求。	

91	GX-B1417/22-P-231764	2023. 12. 20	综合判定：合格。	
92	GX-B1417/22-P-231765	2023. 12. 20	综合判定：合格。	
93	GX-B1417/22-P-231766	2023. 12. 20	综合判定：合格。	

94	GX-B1417/22-P-231767	2023. 12. 20	综合判定：合格。	 A worker wearing a red safety helmet, a blue face mask, and a black jacket is working on a grey gas cylinder mounted on the back of a white vehicle. The worker is holding a tool or hose connected to the cylinder. The background shows an outdoor industrial or construction site with snow on the ground. A timestamp '2023.12.14' is visible in the bottom right corner of the photo.
95	GX-B1306/23-P-23066	2023. 12. 22	综合判定：合格	 A worker wearing a red safety helmet and a grey jacket is working on an electrical panel or control cabinet. The worker is looking at the panel, and there are various wires and components visible. A timestamp '2023.12.11' is visible in the bottom right corner of the photo.
96	GX-B1306/23-P-23067	2023. 12. 22	综合判定：合格	 A worker wearing a red safety helmet is working on a large, complex industrial machine. The machine has various pipes, valves, and components. The worker is positioned in front of the machine, and the background shows an industrial setting. A timestamp '2023.12.11' is visible in the bottom right corner of the photo.

97	GX-B1306/23-P-23068	2023. 12. 22	综合判定：合格	
98	GX-B1306/23-P-23069	2023. 12. 22	综合判定：合格	
99	GX-B1306/23-P-23070	2023. 12. 22	综合判定：合格	

100	GX-B1306/23-P-23071	2023. 12. 22	综合判定：合格	
101	GX-B1417/22-P-231768	2023. 12. 22	综合判定：合格。	
102	GX-B1417/22-P-231769	2023. 12. 22	综合判定：合格。	

103	GX-B1417/22-P-231770	2023. 12. 22	综合判定：合格。	
104	GX-B1417/22-P-231771	2023. 12. 22	综合判定：合格。	
105	GX-B1417/22-P-231772	2023. 12. 22	综合判定：合格。	

106	GX-B1417/22-P-231773	2023. 12. 22	综合判定：合格。	 <p>2023.12.17</p>
107	GX-B1417/22-P-231812	2023. 12. 22	综合判定：合格。	 <p>2023.12.12</p>
108	GX-B1417/22-P-231813	2023. 12. 22	综合判定：合格。	 <p>2023.12.12</p>

109	GX-B1417/22-P-231814	2023. 12. 22	综合判定：合格。	
-----	----------------------	--------------	----------	---