

序号	报告编号	发布日期	结论	影像资料
41	GX-B1304/21-2-24001	2024/1/18	综合判定：合格。	 A photograph showing three workers in grey work clothes and red hard hats standing in an industrial environment. They are positioned near a large piece of machinery with a red component. A date stamp '2024/01/18' is visible in the bottom right corner of the image.
42	GX-B1310/21-2-24001	2024. 1. 18	符合标准要求。	 A photograph showing two workers in safety gear, including red hard hats and high-visibility jackets, standing on a platform with a metal railing. One worker is holding a tool. A silver metal case is on the ground in the foreground. A date stamp '2024/01/18' is visible in the bottom right corner of the image.

43	GX-B1427/21-2-24001	2024. 1. 18	符合标准要求。	
44	GX-B1321/20-2-24002~24009	2024. 1. 22	本次共检电力电缆8条，8条电力电缆所检项目合格。	
45	GX-B1328/20-2-24001	2024. 1. 19	本次共检绝缘手套1副，1副所检项目合格。	

46	GX-B1328/20-2-24002	2024. 1. 19	本次共检绝缘鞋1双，1双所检项目合格。	
47	GX-B1310/21-2-23417	2024. 1. 22	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
48	GX-B1428/21-2-23417	2024. 1. 22	无缺陷迹痕显示。	

49	GX-B1310/21-2-23418	2024. 1. 22	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 A photograph showing a worker in a red helmet and orange pants inspecting a large, curved industrial component. The worker is holding a tool or device against the surface. The date '2024/12/21' is visible in the bottom right corner of the image.
50	GX-B1428/21-2-23418	2024. 1. 22	无缺陷迹痕显示。	 A photograph showing a worker in a red helmet and orange pants inspecting a large, curved industrial component. The worker is holding a tool or device against the surface. The date '2024/12/21' is visible in the bottom right corner of the image.


51	GX-B1517/20-2-23037	2024. 1. 22	综合判定：合格	 <p>2023. 12. 5</p>
52	GX-B1517/20-2-23038	2024. 1. 22	综合判定：合格	 <p>2023. 12. 5</p>

53	GX-B1517/20-2-23039	2024. 1. 22	综合判定：合格。	 A photograph showing the interior of a tunnel. Several workers wearing hard hats and safety gear are visible. There are pipes and cables running along the walls and ceiling. The lighting is dim, with bright spots from the workers' headlamps. A date stamp '2023/12/24' is visible in the bottom right corner of the image.
54	GX-B1517/20-2-23040	2024. 1. 22	综合判定：合格。	 A photograph showing the interior of a tunnel. Several workers wearing hard hats and safety gear are visible. There are pipes and cables running along the walls and ceiling. The lighting is dim, with bright spots from the workers' headlamps. A date stamp '2023/12/24' is visible in the bottom right corner of the image.

55	GX-B1517/20-2-23041	2024. 1. 22	综合判定：合格。	 <p>2023/12/24</p>
56	GX-B1517/20-2-23042	2024. 1. 22	综合判定：合格。	 <p>2023/12/24</p>

57	GX-B1517/20-2-23043	2024. 1. 22	综合判定：合格。	 <p>2023/12/24</p>
58	GX-B1517/20-2-23044	2024. 1. 22	综合判定：合格。	 <p>2023/12/24</p>



59	GX-B1310/21-2-24002	2024. 1. 18	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
----	---------------------	-------------	----------------------------------	---