



序号	报告编号	发布日期	结论	影像资料
43	GX-B1495/20-1-24001~24017	2024. 1. 25	本次共检高压开关设备17台，17台高压开关设备所检项目合格	 A photograph showing three workers in a control room or substation. One worker in the foreground is kneeling and using a handheld device. Two other workers stand in the background. The equipment is labeled with '主墩1路' (Main墩 1路). A yellow date stamp '2024/01/12' is visible in the bottom left corner of the photo.


44	GX-B1383/21-1-24001	2024. 1. 25	所检项目合格	
----	---------------------	-------------	--------	---

45	GX-B1383/21-1-24002	2024. 1. 25	所检项目合格	
46	GX-B1304/21-1-23011	2024/1/24	综合判定：合格	

47	GX-B1303/21-1-23015	2024/1/24	综合判定：合格	
48	GX-B1328/20-1-23132	2024. 1. 25	本次共检绝缘手套120只，120只所检项目合格	

49	GX-B1328/20-1-23133	2024. 1. 25	本次共检绝缘鞋 120只，120只所检项目合格	
50	GX-B1328/20-1-23134	2024. 1. 25	本次共检验电器 10支，10支所检项目合格	

51	GX-B1328/20-1-23135	2024. 1. 25	本次共检短路接地线 10套，10套所检项目 合格	
52	GX-B1328/20-1-23136	2024. 1. 25	本次共检绝缘胶垫60 个，60个绝缘胶垫合 格	

53	GX-B1350/21-1-24001	2024. 1. 25	所检项目合格。	 <p>2024/1/4</p>
54	GX-B1559/22-1-23017	2024. 1. 26	所检项目合格	 <p>2023/12/28</p>

55	GX-B1559/22-1-23018	2024. 1. 26	所检项目合格	
56	GX-B1559/22-1-23019	2024. 1. 26	所检项目合格	
57	GX-B1559/22-1-23020	2024. 1. 26	所检项目合格	

58	GX-B1559/22-1-23021	2024. 1. 26	所检项目合格	
59	GX-B1559/22-1-23022	2024. 1. 26	所检项目合格	

60	GX-B1559/22-1-23023	2024. 1. 26	所检项目合格	
61	GX-B1559/22-1-23024	2024. 1. 26	所检项目合格	


62	GX-B1559/22-1-23025	2024. 1. 26	所检项目合格	
63	GX-B1559/22-1-23026	2024. 1. 26	所检项目合格	

64	GX-B1559/22-1-23027	2024. 1. 26	所检项目合格	
65	GX-B1559/22-1-23028	2024. 1. 26	所检项目合格	

66	GX-B1559/22-1-23029	2024. 1. 26	所检项目合格	
67	GX-B1559/22-1-23030	2024. 1. 26	所检项目合格	

68	GX-B1559/22-1-23031	2024. 1. 26	所检项目合格	
69	GX-B1559/22-1-23032	2024. 1. 26	所检项目合格	

70	GX-B1323/21-1-23256~23265	2024. 1. 26	本次共检三相交流电动机10台，10台三相交流电动机所检项目合格	 A photograph showing a worker in a red hard hat and safety gear working on a piece of electrical equipment. The worker is looking down at the equipment. The date stamp '2023/12/28' is visible in the bottom right corner of the photo.
71	GX-B1352/21-1-245001	2024. 1. 26	所检项目合格。	 A photograph showing a worker in a white hard hat and safety gear working on a piece of electrical equipment. The worker is looking down at the equipment. The date stamp '2024/1/4' is visible in the bottom right corner of the photo.

72	GX-B1322/21-1-24001~24002	2024. 1. 29	本次共检验电力电缆2条，2条所检项目合格	
73	GX-B1520/20-1-24001	2024/1/29	综合判定：合格。	

74	GX-B1520/20-1-24002	2024/1/29	综合判定：合格。	
75	GX-B1520/20-1-24003	2024/1/29	综合判定：合格。	

76	GX-B1307/20-1-23102	2024/1/30	综合判定：合格。	
77	GX-B1307/20-1-23103	2024/1/30	综合判定：合格。	

78	GX-B1307/20-1-23104	2024/1/30	综合判定：合格。	
79	GX-B1307/20-1-23105	2024/1/30	综合判定：合格。	

80	GX-B1307/20-1-23106	2024/1/30	综合判定：合格。	
81	GX-B1307/20-1-23107	2024/1/30	综合判定：合格。	

82	GX-B1307/20-1-23108	2024/1/30	综合判定：合格。	
83	GX-B1307/20-1-23109	2024/1/30	综合判定：合格。	

84	GX-B1307/20-1-23110	2024/1/30	综合判定：合格。	
85	GX-B1451/20-1-24001~24022	2024. 1. 30	本次共检高压开关设备22台，22台高压开关设备所检项目合格	

86	GX-B1321/20-1-23970~23976	2024. 1. 31	本次共检电力电缆 7条，7条电力电缆所 检项目合格	
87	GX-B1321/20-1-23977~23982	2024. 1. 31	本次共检电力电缆 6条，6条电力电缆所 检项目合格	

88	GX-B1321/20-1-23983~23990	2024. 1. 31	本次共检电力电缆 8条，8条电力电缆所 检项目合格	
----	---------------------------	-------------	---------------------------------	---

23045

